

Blackberry 10.6.2616

Release Notes

PrivateGSM - OEM editions - Version 10.6.2616

Fixed Bugs

- [PGBB-746] - Default customer service phone number shown if nothing defined as brand specific

Known Issues

- [PGBB-716] - [OS 7.0] Initial wizard doesn't work with radio OFF - PGSM doesn't connect with radio OFF
- [PGBB-679] - PLATFORM BUG: AMR 4.75 does not work and freeze phone on OS 7.1 devices.
- [PGBB-685] - PLATFORM BUG: Curve 9360 does not manage AMR 4.75, only AMR 12.2
- [PGBB-680] - During a call, loudspeaker menu option has the wrong label on OS 7.1 devices